


## **Daily Update**July 29 and 30

## Repair Work

Devil's Slide (post mile 39.14)

- Excavation work continued to provide access for drilling into the cliff below the road.
- Yerba Buena Construction continued with erosion control work.







Start of hydro seeding

- Electrical contractor St. Francis Electric continued to work on the slide sensor system.
- Maggiora Bros. continued to perform restoration work on the pump and well system.

Slide Location No. 3 (post mile 39.77)

• Construction of the retaining wall at this location continued. More H-beams installed.